








ELBA


01




Instrukcja montażu
Montageanleitung
Instructions D'assemblage
Assembly instructions
Návod na montáž
Montážni návod
Uputstvo za montažu
Upute za montažu



















+ PH2




-





A x 24  Ø8x30 mm	A1 x 4  Ø8x50 mm	A2 x 10  Ø8x20 mm	B x 18  Ø15x12 mm	C x 18  Ø20 mm
F3 x 3  Ø3,0x20 mm	F2 x 1  Ø4,0x20 mm	D x 18  Ø6,5x36,5 mm	E1 x 20  Ø5x16 mm	F x 18  Ø3,5x16 mm
I x 16  15x14x11 mm	K x 2  75x15x32 mm	N7 x 1  Ø8x26 mm	F5 x 10  Ø4,0x40 mm	H5 x 4  Ø3,5x16 mm
W  10 g	X2 x 7  Ø35 mm , KR0	BB x 1  Ø4,5/14x3,5 mm	Q x 5  Ø4,5/Ø14 mm	CC x 3  18x18x8 mm
 FF-1				




1




A2 x 10



Ø8x20 mm



x5






2

F5 x 10






Ø4,0x40 mm





3

D x 6
Ø6,5x36,5 mm








4

D x 6
Ø6,5x36,5 mm








5

A x 4  Ø8x30 mm	D x 1  Ø6,5x36,5 mm	E1 x 6  Ø5x16 mm
--	--	---








6

A x 4  Ø8x30 mm	D x 2  Ø6,5x36,5 mm	E1 x 4  Ø5x16 mm
--	--	---







7

A x 4  Ø8x30 mm	D x 2  Ø6,5x36,5 mm	E1 x 4  Ø5x16 mm
--	--	---







8





D x 1  Ø6,5x36,5 mm	E1 x 6  Ø5x16 mm
--	---







9




10




11




12


F x 4  Ø3,5x16 mm	X2B x 2  Ø35 mm , KR0	
--	--	---



	F  Ø3,5x16 mm	F3  Ø3,0x20 mm	F2  Ø4,0x20 mm	F5  Ø4,0x40 mm
	<i>(Note: Screws F3, F2, and F5 are shown with an 'X' over them, indicating they are not to be used.)</i>			






13

F x 4  Ø3,5x16 mm	X2B x 2  Ø35 mm , KR0	
--	--	---








	F  Ø3,5x16 mm	F3  Ø3,0x20 mm	F2  Ø4,0x20 mm	F5  Ø4,0x40 mm
	<i>(Note: Screws F3, F2, and F5 are shown with an 'X' over them, indicating they are not to be used.)</i>			






14







15



16



17



18

B x 4






Ø15x12 mm


C x 4





Ø20 mm







19



B x 2  Ø15x12 mm	C x 2  Ø20 mm	
---	--	---



20





21




22

I x 16
15x14x11 mm



XX=YY







23


X2A x 7









Ø35 mm , KR0




24



x3



25

F2 x 1  Ø4,0x20 mm	N7 x 1  Ø8x26 mm	Q x 1  Ø4,5/Ø14 mm	BB x 1  Ø4,5/14x3,5 mm	
---	---	---	---	---

